

To: scott.hansen@millelacsband.com[scott.hansen@millelacsband.com]
From: Restaino, Mark
Sent: Mon 7/15/2013 6:22:29 PM
Subject: RE: Emailing: DOC171

Could you tell if the diesel tank had 4" of product or water? According to the paperwork I have the tanks were drained to less than 1" of product back in 2010.

-Mark

-----Original Message-----

From: Scott Hansen [mailto:Scott.Hansen@millelacsband.com]
Sent: Friday, July 12, 2013 2:43 PM
To: Restaino, Mark
Subject: FW: Emailing: DOC171

Mark,

Attached is compliance assistance report from T and J Tire, (Gregg Zimmerman. I verified the product level in all three tanks.

Both unleaded and premium had less than 1 inch of product. The diesel tank had slightly more than four inches. I indicated to Gregg that we needed the product level to be less than 1 inch. I told him I would check back next week to confirm arrangements and then return to verify.

Scott

Scott Hansen
Environmental Program Manager
Mille Lacs Band DNR/E
(320) 532-7445 business
(320) 532-7514 fax
(320) 630 2439 cell

-----Original Message-----

From: Ryan Rupp
Sent: Friday, July 12, 2013 2:14 PM
To: Scott Hansen
Subject: Emailing: DOC171

Your message is ready to be sent with the following file or link attachments:

DOC171

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.